

Connection of PWM pump to older Vitosolic 100 with no PWM control

